MA075863

CATALOGED BY WCOSI-3

UNCLASSIFIED

ADC TECHNICAL REPORT 52:144

CECUDIAL INFO

DO NOT DESTROY
RETURN TO
TECHNICAL DOCUMENT
CONTROL SECTION
WCOSI-3

FILE COPY

4101 F MG

Charles of the control of the contro

EVALUATION OF INSTALLATION
OF
UHF TAIL CAP ANTENNA IN F-86A AND E AIRCRAFT

WILLIAM F. SANDUSKY, MAJOR, USAF ROBERT C. LOLLAR, 2ND LT, USAF

JULY 1952

20011010004

WRIGHT AIR DEVELOPMENT CENTER

UNCLASSIFIED

NOTICES

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

The information furnished herewith is made available for study upon the understanding that the Government's proprietary interests in and relating thereto shall not be impaired. It is desired that the Judge Advocate (WCJ), Wright Air Development Center, Wright-Patterson Air Force Base, Ohio, be promptly notified of any apparent conflict between the Government's proprietary interests and those of others.

The U.S. Government is absolved from any litigation which may ensue from the contractor's infringing on the foreign patent rights which may be involved.

This document contains information affecting the National defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C., Sections 793 and 794. Its transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law.

UNCLASSIFIED



WADC TECHNICAL REPORT 52-144

CCCLD4444PPPPPPPPP

EVALUATION OF INSTALLATION OF UHF TAIL CAP ANTENNA IN F-86A AND E AIRCRAFT

William F. Sandusky, Major, USAF Robert C. Lollar, 2nd Lt, USAF

July 1952

Components and Systems Laboratory SEO No. S-102-54

Wright Air Development Center Air Research and Development Command United States Air Force Wright-Patterson Air Force Base, Ohio





FOREWORD.

THE MATERIAL PRESENTED IN THIS REPORT WAS AUTHORIZED BY AIR RESEARCH AND DEVELOPMENT COMMAND TECHNICAL INSTRUCTION No. 2207-30. Work was initiated as a project of Wright Air Development Center under Service Engineering Order S-102-54, ENTITLED, "Retrofit Installation of Radio Set AN/ARC-27 in USAF Aircraft". The project was administered under the direction of Components and Systems Laboratory of Weapons Components Division, with Major William F. Sandusky acting as assistant project engineer. Flight tests were conducted at Wright-Patterson Air Force Base during the period between 20 February 1952 and 14 March 1952.

INCLUDED AMONG THOSE WHO COOPERATED IN THE TESTS WERE MESSRS. R. T. DOWNEY, C. W. GUELZOW, E. L. BARTON, W. E. LUGINBUHL, ALL MEMBERS OF COMPONENTS AND SYSTEMS LABORATORY, WRIGHT AIR DEVELOPMENT CENTER, AND 1ST LT. W. A. ROSS, FIGHTER FLIGHT TEST SECTION, FLIGHT TEST DIVISION, WRIGHT AIR DEVELOPMENT CENTER.

THIS REPORT IS THE THIRD IN A SERIES ON ULTRA HIGH FREQUENCY ANTENNA FLIGHT TESTS CONDUCTED ON VARIOUS FIGHTER AIRCRAFT. WADC TECHNICAL REPORT NO. 52-70, "EVALUATION OF INSTALLATION OF UHF TAIL CAP ANTENNA IN F-94A AIRCRAFT", AND WADC TECHNICAL REPORT NO. 52-104, "EVALUATION OF INSTALLATION OF UHF TAIL CAP ANTENNA IN F-89 Type AIRCRAFT" ARE THE FIRST AND SECOND REPORTS, RESPECTIVELY, OF THE SERIES.





ABSTRACT

AN ULTRA HIGH FREQUENCY TAIL CAP ANTENNA WHICH WAS FABRICATED AND INSTALLED ON AN F-86A AIRCRAFT BY NORTH AMERICAN AVIATION, INC., WAS SUBJECTED TO FLIGHT TESTS AS OUTLINED IN MILITARY SPECIFICATION MIL-A-6224, "ANTENNA FOR UHF AIRBORNE COMMUNICATIONS EQUIPMENT, GENERAL SPECIFICATION FOR DESIGN OF". THE ANTENNA WAS TESTED ON ULTRA HIGH FREQUENCIES OF 229.2, 316.2, AND 385.6 MEGACYCLES FOR RANGE, AUDIO QUALITY, AND SIGNAL STRENGTH, BOTH AIR-TO-AIR AND AIR-TO-GROUND.

The tests revealed that although there are some areas of low signal strength found forward of the nose and beneath the wings of the aircraft, the antenna provides satisfactory communications, both air-to-air and air-to-ground. The radio frequency input signal strength to the antenna was greater at all times than three microvolts, which was determined by Components and Systems Laboratory to be the minimum acceptable signal strength input for adequate communication reception. Maximum range of the antenna was found to be 260 statute miles while flying on an azimuth heading of 180° from the ground test station and transmitting at a frequency of 229.2 megacycles, and 240 statute miles while flying on an azimuth heading of 180° from the ground test station and transmitting at frequencies of 316.2 and 385.6 megacycles. At all other azimuth headings, the maximum usable range was found to be 210 statute miles at all three test frequencies.

THE TITLE OF THIS REPORT IS UNCLASSIFIED.

PUBLICATION REVIEW

THIS REPORT HAS BEEN REVIEWED AND IS APPROVED.


FOR THE COMMANDING GENERAL:

RIMARD S. CARTER

COLONEL, USAF

ACTING CHIEF, WEAPONS COMPONENTS DIVISION

WADC TR 52-144;



RESTRICTED RESTRICTED

TABLE OF CONTENTS

INTRODUCTION	<u>PAGE</u> 1
INSTALLATION OF EQUIPMENT IN AIRPLANE INSTALLATION OF GROUND STATION EQUIPMENT . BENCH, PREFLIGHT AND FLIGHT TESTS BENCH AND PREFLIGHT TESTS	2
FLIGHT TESTS CONCLUSIONS RECOMMENDATIONS	
	• • • • • • • • • • • • • • • • • • • •
LIST OF ILLUSTRATIONS	
FIGURE	PAGE
1 RIGHT-HAND CONSOLE WITH CONTROL PANEL INSTALLED	C-404/ARC-3
2 RIGHT-HAND CONSOLE WITH CONTROL C-784 3 INSTALLATION OF TRANSMITTER T-67/ARC- R-77/ARC-3 ON THE RETRACTABLE RADIO	/ARC-33 Installed 7 3 and Receiver
4 Installation of Receiver-Transmitter Retractable Radio Support	RT-173/ARC-33 ON
5 VERTICAL TIP ASSEMBLY. (1) HOUSING F	OR UHF TAIL CAP
6 STRAIGHT-LINE TESTS TO AND FROM GROUN 7 STRAIGHT-LINE TESTS TO AND FROM GROUN 229.2 MEGACYCLES	D TEST STATION12 D TEST STATION,
8 STRAIGHT-LINE TESTS TO AND FROM GROUN 316.2 MEGACYCLES.	D TEST STATION,
9 Straight-Line Tests to and from Groun 385.6 Megacycles.	D TEST STATION,
10 CLOVER-LEAF TEST PATTERN. 229.2 MEGACY	CLES. FLEVATION
ANGLE 30°. 12 30° CLOVER-LEAF PATTERN, 316.2 MEGACY	CLES, ELEVATION
ANGLE 300	CLES, ELEVATION
Angle 30°	CLES, ELEVATION
Angle 20°	CLES, ELEVATION
Angle 20°. 16 30° Clover-Leaf Pattern, 385.6 Megacy Angle 20°	cles, Elevation 24
Angle 20°	CLES, ELEVATION
WADO TR 52-144	• •

LIST OF ILLUSTRATIONS CONT'D

FIGURE		PAGE
18	30° CLOVER-LEAF PATTERN, 316.2 MEGACYCLES, ELEVATION	27
19	ANGLE 10°	27 28
20	Angle 10°	SLE
21	Angle 2.35°. 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation	30
22	ANGLE 2.350	31
23	ANGLE 2.35°	32
24	Angle 1.10	33
25	Angle 1.1°	34
•	ANGLE 1.10. 36-Sided Skid Turn Test Pattern.	35 37
26 27	36-Sided Skid Turn Pattern, 229.2 Megacycles, Elevation Angle 1.10	38
28	36-Sided Skid Turn Pattern, 316.2 Megacycles, Elevation	
29	ANGLE 1.1°	39
30	ANGLE 1.10 AIR-TO-AIR TEST PATTERN	40 43
	FLIGHT TEST RECORDS	
No.		PAGE
456		11 16 21 25 29 36 41
と 。		42

INTRODUCTION

Preliminary tests conducted on ultra high frequency tail cap antennas by civilian contractors have indicated that such antennas, when installed in USAF aircraft, have poor distribution in the forward hemisphere. This condition was reported to be particularly bad in the region from 0 to-30° below the nose of the aircraft.

First tests to be made by Wright Air Development Center on standard ultra high frequency antennas were conducted on an ultra high frequency tail cap antenna installed on an F-94A aircraft, (WADC TR No. 52-70, "Evaluation of Installation of UHF Tail Cap Antenna in F-94A Aircraft"). Next, tests were conducted on an ultra high frequency tail cap antenna installed on an F-89C aircraft, (WADC TR No. 52-104, "Evaluation of Installation of UHF Tail Cap Antenna in F-89 Type Aircraft").

Further tests were conducted on a standard ultra high frequency tail cap antenna, North American Aviation Part No. 161-23310-51, which was installed on an F-86A aircraft by North American Aircraft, Inc.. Flight tests were conducted at Wright-Patterson Air Force Base during the period between 20 February 1952 and 14 March 1952.

Since the structure and the radio installation of the F-86E aircraft are similar to the structure and radio installation of the F-86A, the results obtained from the tests on the F-86A will apply to the F-86E, also.

It is believed that the information obtained from these tests will be of assistance to other agencies concerned with the design, installation, and test of ultra high frequency antennas, and with the tactical utilization of the F-86A and E airplanes.

INSTALLATIONS

Installation of Equipment in Airplane

The ultra high frequency radio set AN/ARC-33 and the ultra high frequency tail cap antenna, North American Aviation Part No. 161-23310-51, were installed as a production change in an F-86A, AF Serial No. 48-253. The change consisted of the removal of radio set AN/ARC-3 and the associated cabling, wiring, and antenna, and the installation of: (1) Receiver-Transmitter RT 173/ARC-33 in approximately the same location in the radio compartment as were the Receiver R-77/ARC-3 and Transmitter T-67/ARC-3, (2) radio set control panel C-784/ARC-33 in the cockpit section, and (3) the associated wiring, terminal panels, junction boxes, and ultra high frequency tail cap antenna, North American Aircraft Part No. 161-23310-51.

Receiver-Transmitter RT-173/ARC-33 was connected to the ultra high frequency tail cap antenna by approximately 20 feet of RG-9/U and 15 feet of RG-87/U high-temperature teflon radio-frequency coaxial cable. The tail cap antenna was located in the tip of the vertical stabilizer and was contained within a plastic housing. Figures 1 through 4 show relative positions of the old and new types of radio equipment installed in the F-86 aircraft. The position of the ultra high frequency tail cap antenna on the vertical stabilizer tip is shown in figure 5.

Installation of Ground Test Station

Ground station equipment radio set AN/GRC-27 consisted of one Radio Transmitter T-217/GR () having an indicated power output of 100-125 watts, and one Radio Receiver R-278/GR () having a sensitivity of 1 1/2 to 2 1/2 microvolts. The antenna which was used was antenna AS-505/GR (), commonly called, "Squirrel Cage UHF Antenna". The antenna was mounted 70 feet above the ground and connected to the AN/GRC-27 ground installation by an 80-foot frequency cable RG-17A/U.

The radio frequency signal intensities were measured across the automatic volume control to the ground in the Radio Receiver R-278/GR by means of a vacuum tube voltmeter. This voltage was then reduced to receiver input voltage by a calibrated signal source (Signal Generator Hewlett-Packard Model 608A) to produce the same automatic volume control to ground voltage. The relation

<u>Ein</u> = K Eout

was used to obtain the conversion factor by which signal intensities, across the automatic volume control to ground, were reduced to receiver input intensity.

BENCH, PREFLIGHT, AND FLIGHT TESTS

Bench and Preflight Tests

Radio Set AN/ARC-33 was bench and preflight tested essentially in accordance with the tentative USAF Specification MIL-R-7238, "Radio Set AN/ARC-33, Bench, Preflight, and Flight Test of". The only deviation made from the specification was that the squelch circuit on the Receiver-Transmitter RT-173/ARC-33 was completely turned off. This was done to obtain more reliable signal strength recordings at the ground test station. Otherwise, the AN/ARC-33 was tested in accordance with the specification and was found to meet the requirements stated therein.

Flight Tests

1. General:

The evaluation of the ultra high frequency tail cap antenna was based upon flight test configurations as outlined in Specification MIL-A-6224, entitled "Antenna for UHF Airborne Communications Equipment, General Specification for Design of". The only deviation from the specification was to permit even more comprehensive tests than those required by the specification. The three

assigned test frequencies for all flight tests were 229.2, 316.2, and 385.6 megacycles. Flight configurations which were flown were straight-line tests, clover-leaf patterns, 36-sided skid turn patterns, maximum range tests, and air-to-air tests.

2. Straight-Line Tests:

The flight test pattern for the straight-line tests is shown in figure 6, and Flight Test Record No. 1 (P.11) is the detailed description of the flight. The F-86A climbed to an altitude of 40,000 feet and assumed a 180-degree heading to the ground test station AF5XX directly below. The pilot then notified the ground station when he was at this position, and proceeded to fly on this heading for 50 nautical miles, reporting to the ground station every 30 seconds, while holding the carrier wave on for approximately three seconds. After reaching the 50-nautical mile point, the pilot executed a 180-degree turn and repeated the same procedure on a 0-degree heading. This test was made for all assigned test frequencies.

Results of the straight-line tests, shown in figures 7, 8, and 9, indicate that the signal strength recordings were never below the acceptable three- microvolt minimum. At both headings, when the aircraft was in an area of from one to two nautical miles from the ground test station AF5XX, there was a pronounced amount of garbling which made communication extremely variable. This condition of garbling did not prevail directly over the ground test station as it did in both the F-94A and F-89C tests, which probably can be attributed to the swept-back configuration of the empennage section of the aircraft. Communication was of a high degree of intelligibility at all other aircraft positions.

3. Clover-Leaf Patterns:

The typical flight pattern used to conduct the clover-leaf tests is illustrated in figure 10. (This figure shows a 45-degree pattern, while the tests included only 30-degree clover-leaf patterns.) The purpose of the clover-leaf tests was to determine signal strength data and the quality of communication at various azimuth headings and elevation angles to the ground test station. Tests were conducted at five different elevation angles from the ground station, and all three assigned test frequencies were used in each flight pattern.

Flight Test Record No. 2 (P.16) is the individual record of the pattern flown at the relatively high elevation angle of 30 degrees. Figures 11, 12, and 13 are the antenna signal strength plots for the three test frequencies of 229.2, 316.2, and 385.6 megacycles, respectively. Although the antenna signal strength plots indicate a slight nose null at all test frequencies, the results show that at no time were the recordings below the acceptable three-microvolt minimum, and communication was of a high quality throughout the tests.

Flight Test Record No. 3 (P. 21) is the detailed description of the 30-degree clover-leaf pattern flown at the elevation angle of 20 degrees, and figures 14, 15, and 16 are the signal strength plots for each of the three test frequencies. These plots show that although a slight nose null still existed, a more symmetrical pattern was obtained than was obtained in the test flown at a 30-degree elevation angle.

Flight Test Record No. 4 (P.25) is the detailed report of the 30-degree clover-leaf pattern flown at an elevation angle of 10 degrees. Figures 17, 18, and 19 show the antenna signal strength plots for the tests flown at 229.2, 316.2, and 385.6 megacycles, respectively. Results again indicated that a shadowing of the antenna occurs off the nose of the aircraft, although the signal strength recordings were above the three-microvolt acceptable minimum at all times.

The detailed information of the 30-degree clover-leaf patterns flown at the low elevation angles of 2.35 and 1.1 degrees is recorded in flight test record No. 5, (P.29). Figures 20, 21, and 22 are the antenna signal strength plot patterns for the pattern flown at the 2.35-degree elevation angle, and figures 23, 24, and 25 are those flown at the 1.1-degree elevation angle. The results of these tests indicated that the antenna signal strengths were well above the three-microvolt acceptable minimum at all azimuth headings for both elevation angles.

4. 36-Sided Skid Turn Patterns:

Figure 26 illustrates the typical flight pattern used for the 36-sided skid-turn pattern tests, and figures 27, 28, and 29 are the antenna signal strength plots for the three assigned test frequencies, 229.2, 316.2, and 385.6 megacycles, respectively. These tests were conducted to further investigate the antenna radiation pattern at the low elevation angle of 1.1 degrees which was previously checked by flying a 30-degree clover-leaf pattern. Detailed information for this flight is recorded in flight test record No. 6, (P.36). The results obtained when these 36-sided skid turn patterns were being flown agree with those recorded for the 30-degree clover-leaf patterns in that a slight nose mull was evident on all three test frequencies, although the signal strength recordings were above the three-microvolt minimum at all times.

5. Maximum Range Tests:

Maximum range tests were conducted to determine the maximum two-way communication range of the ultra high frequency tail cap antenna used in conjunction with radio set AN/ARC-33 installed on an F-86A aircraft. Detailed information of the flight is recorded in flight test record No. 7, (P.41).

The pilot flew at an altitude of 35,000 feet at a 180-degree heading from the ground station AF5XX, maintaining continuous contact with the station until the transmitted signal received at the station was just less than three microvolts. At this point, the pilot executed a 180-degree turn and flew a 0-degree heading to the station until the three-microvolt signal level was reached.

The maximum usable range of the ultra high frequency tail cap antenna on the F-86A aircraft was found to be 260-statute miles with a 180-degree heading to the station at 229.2 megacycles, 240-statute miles at a 180-degree heading to the station at both 316.2 and 385.6 megacycles, and 210-statute miles for all other azimuth headings to the ground station at all three test frequencies.

6. Air-to-Air Test:

The flight pattern used for the air-to-air tests is shown in figure 30. The airborne test station, which was an F-89C aircraft equipped with an ultra high frequency tail cap antenna, flew a 35-mile radius circle around the ground test station at an altitude of 35,000 feet (see Fig. 30, track A). The F-86A airplane being tested was flown at an altitude of 15,000 feet in a 7 1/2-mile radius circle over a ground reference point which was 35 miles from the ground test station (see Fig. 30, track B). The pilots of the two aircraft maintained continuous two-way conversation with each other, reporting their locations and headings at all times. The ground test station recorded the conversation on tape. This pattern was flown for the three assigned test frequencies. A detailed account of the test is shown in Flight Test Record No. 8, (P. 42).

Results of this test revealed that the quality and strength of communication were very good at all times. It is important to note that the squelch circuit on the Receiver-Transmitter RT-173/ARC-33 was cut off as described in the section entitled "Bench and Preflight Tests" of this report, (P. 2).


CONCLUSIONS

Results of the flight tests can be summarized as follows:

- A. The ultra high frequency tail cap antenna as installed in F-86A and E aircraft and used in conjunction with Radio Set AN/ARC-33 provides satisfactory two-way communication throughout the entire frequency band of the ultra high frequency communications equipment, at all ground station to aircraft elevation angles, at all azimuth headings, and in all positions of other aircraft above the F-86A and E aircraft.
- B. It must be noted that it is most important to thoroughly check the ground station antenna pattern to determine the areas of low sensitivity resulting from improper antenna height and ground reflections.

RECOMMENDATIONS


It is recommended that the ultra high frequency tail cap antenna, North American Part No. 161-23310-51, be installed on all F-86A and E aircraft.



1. Right-Hand Console with Control Panel C-404/ARC-3 Installed

WADC TR 52-1144


RESTRICTED



WADC TR 52-144

RESTRICTED


Right-hand Console with Control Panel C-784/ARC-33 Installed Fig. 2.



Installation of Transmitter T-67/ARG-3 and Receiver R-77/ARC-3 on the Retractable Radio Support


WADC TR 52-144

RESTRICTED



Installation of Receiver-Transmitter RT-173/ARC-33 on Retractable Radio Support **4.** में है.

WADC TR 52-144



WADC TR 52-144

RESTRICTED

(1) Housing for UHF Tail Cap Antenna Vertical Tip Assembly.

Fig. 5.

FLIGHT TEST RECORD NO. 1

Airplane Type and No...F-86A,

AF No..48-253

Flight No.....1

Project...UHF Tail Cap Antenna
Evaluation, Straight Line Tests

E.O. No....S-102-54

Time...

Take-off......0901

<u>Location</u>....Local Landing......1104

Max. Altitude....40,000 ft.

Total on Equip..2+03

Weather.....VFR Pilot..lst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To obtain signal strength data and to check on the quality of two-way communication off the nose and tail of the aircraft at various elevation angles from ground test station AF5XX.

Test Procedure and/or Flight Program: The pilot climbed to 40,000 ft. and assumed a position directly over the ground test station AF5XX. At this point, the pilot notified the ground test station, then proceeded to fly 180° from the station, reporting every 30 seconds. This procedure continued until the aircraft was 50 nautical miles from the ground test station, where the pilot executed a 180° turn and flew a 0° heading to the ground test station, again reporting every 30 seconds. The ground test station recorded the signal strengths received. This test was conducted at test frequencies of 229.2, 316.2, and 385.6 megacycles.

Test Data and/or Results: The signal strength recordings were good throughout the three frequencies tested at all elevation angles to the ground test station. Communication was excellent during the tests except at points between one and two miles of the ground station where garbling occurred.




Fig. 6. Straight Line Tests to and from Ground Test Station

BD = Actual Flight Path of Aircraft

M = 50 Nautical Miles

H = Altitude of Flight Path = 41,000 ft.(Pressure)





Fig. 7. Straight-Line Tests to and from Ground Test Station 229.2 Megacycles

KEY
--- Nose Heading
Tail Heading


Aircraft - F-86A AF No. 48-253 Date - 12 March 1952 Pilot - Lt. W. A. Ross Operator - W. E. Luginbuhl



RANGE - NAUTICAL MILES

Fig. 8. Straight-Line Tests to and from Ground Test Station 316.2 Megacycles

Aircraft - F-86A AF No. 48-253 Date - 12 March 1952 Pilot - Lt. W. A. Ross Operator - W. E. Luginbuhl



RANGE - NAUTICAL MILES

Fig. 9. Straight-Line Tests to and from Ground Test Station 385.6 Megacycles

KEY -----Nose Heading Tail Heading

Aircraft - F-86A AF No. 48-253 Date - 12 March 1952 Pilot - Lt. W. A. Ross Operator - W. E. Luginbuhl

FLIGHT TEST RECORD NO. 2

Project...UHF Tail Cap Antenna Airplane Type and No...F-86A, Evaluation, 30° Clover Leaf AF No.48-253 Pattern Tests E.O. No....S-102-54 Flight No....2 Time.... Date....26 February 1952 Take-off......1230 Location....Local Landing......1345 Total Flight....1+15 Max. Altitude 40,000 ft. Total on Equip..1+15 Weather....VFR Pilot..lst Lt. W.A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To obtain signal strength recordings and to check the quality of two-way communication while flying at various azimuth bearings and at an elevation angle of 30° to the ground test station AF5XX.

Test Procedure and/or Flight Program: The pilot climbed to 40,000 ft. at a point 12.5 nautical miles from ground station AF5XX, flew a 30° clover leaf pattern over this point, and reported to the ground test station on every leg of the pattern over the ground reference point. The ground station recorded the signal strength data. This test was conducted at test frequencies of 229.2, 316.2, and 385.6 megacycles.

Test Data and/or Results: The signal strength recordings were good, and all were above the acceptable three microvolt minimum. The quality of the two-way communication was good at all three test frequencies.




Fig. 10. Clover-Leaf Test Pattern

h = Altitude of flight pattern

d = Distance of ground reference point to ground test station θ = Arc tan $\frac{h}{d}$ = ground station to aircraft elevation angle

NOTE: Pattern illustrated is a 45° Clover-Leaf, while the patterns flown for the subject tests were 30° Clover-Leaf.




Fig. 11 30° Clover-Leaf Pattern, 229.2 Megacycles, Elevation Angle 30°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 12.5 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 12 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation Angle 30°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 12.5 nautical miles Date - 26 February 1952 Pilot - lst Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 13 30° Clover-Leaf Pattern, 385.6 Megacycles, Elevation Angle 30°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 12.5 nautical miles Date - 26 February 1952

Pilot - lst Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

FLIGHT TEST RECORD NO. 3

Airplane Type and NoF-86A, AF No48-253	ProjectUHF Tail Cap Antenna Evaluation, 30° Clover Leaf Pattern Tests
Flight No3	E.O. NoS-102-54
Date27 February 1952	<u>Time</u> Take-off0825
LocationLocal	Landing1015
Non- 41444444 /0 000 At	Total Flight1+55
Max. Altitude40,000 ft.	Total on Equip1+55
WeatherVFR	Pilotlst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft

<u>Purpose or Description of Flight</u>: To obtain signal strength data and to check the quality of two-way communication at various azimuth bearings and at a 20° elevation angle to the ground test station.

Test Procedure and/or Flight Program: The pilot climbed to 40,000 ft. and flew to a point 20 nautical miles from ground station AF5XX. This point was the ground reference point where 30° clover-leaf patterns were flown at the three test frequencies of 229.2, 316.2, and 385.6 megacycles. The pilot reported to the ground test station on each leg of each pattern over the ground reference point. The ground test station recorded the signal strength data.

Test Data and/or Results: The signal strength recordings were all well above the acceptable three-microvolt minimum, and the quality of communication at all times was very good.




Fig. 14 30° Clover-Leaf Pattern, 229.2 Megacycles, Elevation Angle 20°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 15 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation Angle 20°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Inginbuhl Remarks - Good two-way communication throughout entire flight pattern

WADC TR 52-144

23

RESTRICTED




Fig. 16 30° Clover-Leaf Pattern, 385.6 Megacycles, Elevation Angle 20°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 40,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

FLIGHT TEST RECORD NO. 4

Airplane Type and NoF-86A, AF No48-253	ProjectUHF Tail Cap Antenna Evaluation, 30° Clover-Leaf Pattern Tests
Flight No4	E.O. NoS-102-54
Date27 February 1952	<u>Time</u> Take-off1500
LocationLocal	Landing1615
	Total Flight1+15
Max. Altitude 35,000 ft.	Total on Equip1+15
WeatherVFR	Pilotlst Lt. W. A. Ross

Equipment under Test: Receiver- Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To obtain signal strength data, and to check the quality of two-way communication at various azimuth bearings and at an elevation angle of 10° from the ground test station.

Test Procedure and/or Flight Program: The pilot climbed to 35,000 ft. and flew to a point 33 nautical miles from the ground test station AF5XX. Using this point as a ground reference point, the pilot flew 30° clover-leaf patterns at 229.2, 316.2, and 385.6 megacycles, and reported the azimuth heading to the ground test station on each leg of each pattern. The ground station recorded the signal strength data.

Test Data and/or Results: The recorded signal strengths were all above the minimum acceptable strength of three microvolts, and the quality of the two-way communications was very good at all times.




Fig. 17 30° Clover-Leaf Pattern, 229.2 Megacycles, Elevation Angle 10°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 35,000 ft. (Pressure) Distance - 34 nautical miles Date - 28 February 1952 Pilot - lst Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 18 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation Angle 10°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 35,000 ft. (Pressure) Distance - 34 nautical miles Date - 28 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 19 30° Clover-Leaf Pattern, 385.6 Megacycles, Elevation Angle 10°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 35,000 ft. (Pressure) Distance - 34 nautical miles Date - 23 February 1952 Pilot - lst Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

WADC TR 52-144

28

RESTRICTED

FLIGHT TEST RECORD NO. 5

Airplane Type and NoF-86A, AF No48-253	ProjectUHF Tail Cap Antenna Evaluation, 30° Clover-Leaf Pattern Tests
Flight No5	E.O. NoS-102-54
Date28 February 1952	Time Take-off0813
LocationLocal	Landing0945
15 47484m3a	Total Flight1+32
Max. Altitude6,000 ft.	Total on Equip1+32
WeatherVFR	Pilotlst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To obtain signal strength data and to check the quality of two-way communication at various azimuth bearings and at the two elevation angles of 2.35° and 1.1° from the ground test station.

Test Procedure and/or Flight Program: The pilot climbed to an altitude of 6,000 ft. and flew 30° clover-leaf patterns at the three test frequencies of 229.2, 316.2, and 385.6 megacycles at distances of 20 and 40 nautical miles from the ground test station. The pilot reported the azimuth heading on each leg of each pattern over the ground reference points and ground station AF5XX recorded the signal strength data.

Test Data and/or Results: The results revealed that the radiation pattern of the tail cap antenna at all test frequencies, azimuth headings, and the two elevation angles, was well above the three-microvolts acceptable minimum. The quality of communications was good at all times during the test flights.




Fig. 20 30° Clover-Leaf Pattern, 229.2 Megacycles, Elevation Angle 2.35°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 6,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

WADC TR 52-144

30




Fig. 21 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation Angle 2.35° Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 6,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Inginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 22 30° Clover-Leaf Pattern, 385.6 Megacycles, Elevation Angle 2.35°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 6,000 ft. (Pressure) Distance - 20 nautical miles Date - 26 February 1952 Pilot - lst Lt. W. A. Ross Operator - W. E. Lubinbuhl Remarks - Good two-way communication throughout entire flight pattern

WADC TR 52-144

32




Fig. 23 30° Clover-Leaf Pattern, 229.2 Megacycles, Elevation Angle 1.1°

Scale: | 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 6,000 ft. (Pressure) Distance - 40 nautical miles Date - 26 February 1952 Pilot - lst Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 24 30° Clover-Leaf Pattern, 316.2 Megacycles, Elevation Angle 1.1°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap
Aircraft - F-86A AF No. 48-253
Altitude - 6,000 ft. (Pressure)
Distance - 40 nautical miles
Date - 26 February 1952

Pilot - 1st Lt. W. A. Ross Operator - W. E. Inginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 25 30° Clover-Leaf Pattern, 385.6 Megacycles, Elevation Angle 1.1°

Scale: 1 Division = 4 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 6,000 ft. (Pressure) Distance - 40 nautical miles Date - 26 February 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

FLIGHT TEST RECORD NO. 6

Airplane Type and No...F-86A, Project... UHF Tail Cap Antenna AF No..48-253 Evaluation, 36-Sided Skid Turn Pattorn Tests Flight No.....6 E.O. No....S-102-54 Date....28 February 1952 Time.. Take-off......1320 Location....Local Landing......1435 Total Flight....1+15 Max. Altitude....11,000 ft. Total on Equip..1+15 Weather....VFR Pilot..lst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To obtain signal strength data and to check the quality of two-way communication at various azimuth headings and at a low elevation angle of l.l from the ground test station AF5XX.

Test Procedure and/or Flight Program: The pilot climbed to 11,000 ft. and flew to a ground reference point of 86 nautical miles from the ground test station AF5XX. Over this point the pilot flew 36-sided skid turn patterns, using the test frequencies of 229.2, 316.2, and 385.6 megacycles. The ground test station recorded the signal strength data.

Test Data and/or Results: The test data revealed that although some slight mull areas did exist forward of the nose and off the wings of the aircraft, the signal strength recordings were well above the three-microvolt minimum, and the quality of communications was good at all times.




Fig. 26. 36-Sided Skid Turn Test Pattern

h = Altitude of flight pattern

d = Distance of ground reference point to ground test station

 Θ = Arc tan $\frac{h}{d}$ = ground station to aircraft elevation angle




Fig. 27 36-Sided Skid Turn Pattern, 229.2 Megacycles, Elevation Angle 1.1°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 11,000 ft. (Pressure) Distance - 86 nautical miles Date - 7 March 1952 Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

WADC TR 52-144




Fig. 28 36-Sided Skid Turn Pattern, 316.2 Megacycles, Elevation Angle 1.1°

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 11,000 ft. (Pressure) Distance - 86 nautical miles

Date - 7 March 1952

Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern




Fig. 29 36-Sided Skid Turn Pattern, 385.6 Megacycles, Elevation Angle 1.10

Scale: 1 Division = 2 Microvolts

Antenna Type - Tail Cap Aircraft - F-86A AF No. 48-253 Altitude - 11,000 ft. (Pressure) Distance - 86 nautical miles

Date - 7 March 1952

Pilot - 1st Lt. W. A. Ross Operator - W. E. Luginbuhl Remarks - Good two-way communication throughout entire flight pattern

FLIGHT TEST RECORD NO. 7

Airplane Type and NoF-86A, AF No48-253	Project UHF Tail Cap Antenna Evaluation, Maximum Range Tests
Flight No7	E.O. NoS-102-54
Date28 February 1952	Time Take off1500
LocationLocal	Landing1618
Max. Altitude35,000 ft.	Total Flight1+18
	Total on Equip1+18
WeatherVFR	Pilotlst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To determine the maximum two-way communication range of the ultra high frequency tail cap antenna.

Test Procedure and/or Flight Program: The pilot climbed to 35,000 ft., flew a course 180° from the ground test station AF5XX, reporting positions at frequent intervals, and flew this heading until the ground station reported that the three-microvolt minimum signal strength had been received, thus determining the maximum range with a tail bearing to the ground test station. Then the pilot executed a 180° turn and flew until the ground station reported that the three-microvolt minimum had been reached, thus determining the maximum range with a nose bearing to the ground test station. This test was conducted at all three test frequencies, 229.2, 316.2, and 385.6 megacycles.

Test Data and/or Results: The maximum usable ranges of the antenna are as follows:

Frequency	Azimuth Bearing to AF5XX	Max. Range in <u>Statute Miles</u>
229.2 mc	180°	260
	All others	210
316.2 mc	180°	240
	All others	210
385.6 mc	180°	240
-	All others	210
WADC TR 52-144	۲۱	

FLIGHT TEST RECORD NO. 8

Airplane Type and NoF-86A, AF No48-253	<u>Project</u> UHF Tail Cap Antenna Evaluation, Air-to-Air Tests
Flight No8	E.O. NoS-102-54
<u>Date</u> 4 March 1952	<u>Time</u> Take-Off0930
LocationLocal	Landinglll0
Max. Altitude 35,000 ft.	Total Flightl+40
	Total on Equip1+40
WeatherVFR	Pilot., lst Lt. W. A. Ross

Equipment under Test: Receiver-Transmitter RT-173/ARC-33 in conjunction with the ultra high frequency tail cap antenna as installed in an F-86A aircraft.

<u>Purpose or Description of Flight</u>: To determine the strength and quality of two-way communication above the F-86A at various azimuth headings and distances. This was accomplished by using an F-89C aircraft equipped with a tail cap antenna as the airborne test station.

Test Procedure and/or Flight Program: The F-89C flew a 70-mile diameter circle at 35,000 ft. over ground test station AF5XX. The F-86A flew a 15-mile diameter circle at 15,000 ft., and at a distance of 35 miles from the ground test station. The pilots of the two aircraft maintained continuous radio contact with each other and the ground test station recorded the conversation on tape. This test was conducted at the three test frequencies of 229.2, 316.2, and 385.6 megacycles.

Test Data and/or Results: The strength and quality of the two-way communication were very satisfactory at all test frequencies throughout the flight patterns.




Fig. 30. Air-to-Air Test Pattern

A - Track of F-890 airborne test station B - Track of F-86A aircraft under test

h = 35,000 ft. (Pressure) h'= 15,000 ft. (Pressure)

DISTRIBUTION LIST

Cys	ACTIVITIES AT W-P AFB	Cys	Activities
4 1 2	BAGR_CD, ATTN: Mrs. D. Martin WCAPP DSC_SA	1	AF Engineering Field Representative Code 1110, Naval Research Lab.
2	MCMMGT	,	ATTN: Lt. Col. M. N. Abramovich Washington 25, D. C.
2	MCMMGR, ATTN: Mr. Michaelson	5	Commanding General Edwards Air Force Base,
2	мсрраа43		California
5	WCEN	5	Commanding Officer Holloman Air Force Base
1	WCENE-4		New Mexico
1	WCEOS, ATTN: Dr. P. B. Taylor	1	Commanding General Air Proving Ground Command
3	WCEOT_1		ATTN: Class. Tech Data Br D/OI Eglin Air. Force Base, Florida
1	WCER, ATTN: Mr. George Rappaport	10	Commanding General
ı	WCERD		Strategic Air Command ATTN: Operations Analysis
25	WCESO-2.		Office Offutt Air Force Base
2	WCRR (For RAND Corp.)		Nebraska
5	WCSWF	10	Commanding General Tactical Air Command
	OTHER DEPT. OF DEFENSE ACTIVITIES		Langley Air Force Base, Virginia
	Air Force	1	Commanding General
10	Commanding General Air Research and Development Command ATTN: RDOL	1	Air Force Cambridge Research Center ATTN: ERRS-3 230 Albany Street
	P. O. Box 1395 Baltimore 1, Maryland		Cambridge 39, Massachusetts
	TOTAL OF TOTAL	1	Commanding General
1	Director of Research and Development Headquarters, USAF		Rome Air Development Center ATTN: ENR Griffiss Air Force Base,
	Washington 25, D. C.		Rome, New York

DISTRIBUTION LIST Cont'd

			•
Cys	<u>Activities</u>	Cys	<u>Activities</u>
1	Director Air University Library ATTN: Req. CR-3998 Maxwell Air Force Base, Alabama	1	Bureau of Aeronautics General Representative Cornell Aeronautical Lab. Box 235 Buffalo, New York
10	Director of Communications and Electronics Air Defense Command ATTN: AC&W Coordinating Div. Ent Air Force Base Colorado Springs, Colorado	1	Bureau of Aeronautics General Representative Goodyear Aircraft Corporation 1210 Massillon Road Akron 15, Ohio
1	Washington AF Eng Field Office Room 4949, Main Navy Bldg., Department of the Navy Washington 25, D. C.	1	Chief, Bureau of Ordnance Department of the Navy ATTN: Code AD-3 Washington 25, D. C.
	Army	1	Chief, Bureau of Ships Department of the Navy
2	Commanding Officer Signal Corps Eng Laboratory ATTN: Technical Reports		ATTN: Technical Data Section Washington 25, D. C.
	Library Fort Mormouth, New Jersey	1	Chief of Naval Operations Department of the Navy ATTN: OP-42-B2
1	OCSigO (SIGGD) Engineering and Technical Div.		Washington 25, D. C.
•	Washington 25, D. C. Navy	1	Commander U. S. Naval Ordnance Laboratory Silver Spring 19, Maryland
3	Bureau of Aeronautics General Representative Consolidated-Vultee Aircraft Corp. San Diego 12, California For Processing to Ryan Aeronautical Company	6 1 1	Chief of Naval Research Department of the Navy Washington 25, D. C. ATTN: Planning Div., Code N-482 ATTN: Elec. Section, Code 427 Commander U. S. Naval Air Development Center
. 1	Bureau of Aeronautics General Representative Chance-Vought Aircraft Div. United Aircraft Corp. Naval Industrial Reserve Plant Dallas. Texas		ATTN: Electronics Laboratory Johnsville, Pennsylvania

Dallas, Texas

DISTRIBUTION LIST Cont'd

Cys	<u>Activities</u>	Cys	Activities
1	Commander U. S. Naval Ordnance Test Station Inyokern, China Lake, California	1	Mr. L. G. DeBay Ballistic Research Laboratory Aberdeen Proving Ground Maryland
1	CO & Director U. S. Navy Electronics Laboratory San Diego 52, California	1	Dr. Roy C. Spencer Air Force Cambridge Research Center 230 Albany Street Cambridge 39, Massachusetts
1	Commander U. S. Naval Air Missile Test Center Point Mugu, California	1	Dr. J. I. Bohnert U. S. Naval Research Laboratory Washington 25, D. C.
2	Director U. S. Navy Electronics Laboratory ATTN: Dr. T. J. Keary, Code 230	2	Dr. A. G. McNish National Bureau of Standards Washington 25, D. C.
	Point Loma, San Diego 52, California	2	Mr. H. G. Lindner Coles Signal Laboratory Red Bank, New Jersey
1	Director U. S. Naval Research Laboratory ATTN: Technical Data Section Washington 25, D. C.	2	Mr. O. C. Woodyard Evans Signal Laboratory Belmar, New Jersey
1	Superintendent U. S. Naval Academy Post Graduate School Annapolis, Maryland Research and Development Board	3	Dr. J. V. Granger Aircraft Radiation Systems Lab. Stanford Research Institute Stanford, California
1	Committee on Electronics, Research and Development Board ATTN: Secretary, Panel on Radiation Systems National Defense Building Washington 25, D. C.	2	Dr. V. H. Rumsey The Ohio State University Research Foundation 310 Administration Building Ohio State University Columbus 10, Ohio Dr. E. C. Jordan
2	Research and Development Board Library Branch, Info. Offices ATTN: C. R. Flagg, Rm 3D1041 The Pentagon Washington 25, D. C.		University of Illinois Urbana, Illinois



DISTRIBUTION LIST Cont'd

Сув	<u>Activities</u>	Cys	Activities
1	Special Projects Document Room Project LINCOLN Massachusetts Inst. of Technology	3	Chase Aircraft Co., Inc. ATTN: Chief Engineer DeCou and Parkaway Aves. Hangar Building 34 Mercer County Airport West Trenton, New Jersey
	P. 0. Box 390 Cambridge 39, Massachusetts ATTN: Ethel R. Branz OTHERS	2	Consolidated-Vultee Aircraft Corporation ATTN: Chief Engineer Fort Worth 1, Texas
2	Federal Telecommunications Laboratory 500 Washington Avenue Nutley, New Jersey	2	Consolidated-Vultee Aircraft Corporation ATTN: Chief Engineer San Diego Division San Diego, California
1	Airborne Instruments Lab., Inc. ATTN: Mr. E. L. Bock, Antenna Section 160 Old Country Road Mineola, Long Island, New York	2	Dalmo Victor Company ATTN: Mr. Glenn Walters 1414 El Camino Real San Carlos, California
3	Antenna Research Laboratory, Inc. ATTN: D. C. Cleckner 797 Thomas Lane Columbus 2, Ohio	1	Dorne and Margolin Grumman Airfield Bethpage, Long Island, New York
· 1	Beech Aircraft Corporation ATTN: Chief Engineer 6600 E. Central Avenue Wichita 1, Kansas	2	Douglas Aircraft Company, Inc. ATTN: Chief Engineer 3000 Ocean Park Blvd. Santa Monica, California
2	Bell Aircraft Corporation ATTN: Chief Engineer P. O. Box 1 Buffalo, New York	2	Douglas Aircraft Company, Inc. ATTN: Chief Engineer 3855 Lakewood Blvd. Long Beach, California
4	Boeing Airplane Company ATTN: Chief Engineer Wichita Division Wichita 1, Kansas	2	Douglas Aircraft Company, Inc. ATTN: Chief Engineer 827 Lapham Street El Segundo, California
2	Boeing Airplane Company ATTN: Mr. G. Hollingsworth Seattle Division Seattle 14, Washington	1	Electronics Research Lab., Inc. Diamond and Kentucky Avenue Science Park Evansville 4, Indiana
	··· ·· · · · · · · · · · · · · · · · ·	_	



UNCLASSIFIED

DISTRIBUTION LIST Cont'd

Fairchild Engine and Airplane Corp. ATTN: Chief Engineer Hagerstown, Maryland Grumman Aircraft Eng. Corp. ATTN: Chief Engineer Bethpage, Long Island, New York Haghes Aircraft Company Florence Ave. at Teale St. Culver City, California ATTN: Mr. N. H. Enenstein ATTN: Mr. John T. Milek Lockheed Aircraft Corporation ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri MeDonnell Aircraft Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Clenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer ACO E. Fifth Avenue Columbus 16, Ohio North American Aviation ATTN: Los Ageles, California ATTN: Dr. J. A. Marsh Aerophysics Lab. Northrop Aircraft, Inc. ATTN: Chief Engineer Hawthorne, California Panthorne, California Rath Corporation ATTN: Librarian Librarian Librarian Librarian Librarian Los Angeles, California ATTN: Chief Engineer Hawthorne, California Los Antone, California Los Antone, Marthorne, California Los Antone, California Los Antone, Marthorne, California Los Antone, California Los Antone, Marthorne, California Los Antone, Chief Engineer Hawthorne, California Los Antone, Marthorne, Chief Engineer Hawthorne, California Los Antone, Marthorne, Chief Engineer Hawthorne, California Los Antone, Marthorne, California Los Antone, Marthorne, Chief Engineer Hawthorne, California Los Antone, Marthorne, Marthorne, Chief Engineer Hawthorne, California L	Cys	Activities	Cys	Activities
Grumman Aircraft Eng. Corp. ATTN: Chief Engineer Bethpage, Long Island, New York Hughes Aircraft Company Florence Ave. at Teale St. Culver City, California ATTN: Dr. L. C. VenAtta ATTN: Mr. N. H. Enenstein ATTN: Mr. John T. Milek Lockheed Aircraft Corporation ATTN: Chief Engineer 2555 Hollywood Way Burbank, California McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer A300 E, Fifth Avenue Columbus 16, Ohio Aerophysics Iab. Aerophysics Iab. ATTN: Chief Engineer Havthorne, California ATTN: Librarian L500 4th Street Santa Monica, California ATTN: Librarian L500 4th Street Santa Monica, California ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts Werkshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	3	Corp. ATTN: Chief Engineer	3 2	International Airport Los Angeles, California ATTN: Engineering Data Sec.
Hughes Aircraft Company Florence Ave. at Teale St. Culver City, California 1 ATTN: Dr. L. C. VanAtta 1 ATTN: Mr. N. H. Enenstein 1 ATTN: Mr. John T. Milek 5 Lockheed Aircraft Corporation ATTN: Chief Engineer 2555 Hollywood Way Burbank, California 3 McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri 5 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 6 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio ATTN: Dibrarian ATTN: Librarian 1500 4th Street Santa Monica, California ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts ATTN: Mr. Louis 3, Missouri 4 Republic Aviation Corp. ATTN: Military Contracts Dept. Farmingdale, Long Island, New York New York Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 Morkshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	3	ATTN: Chief Engineer		Aerophysics Lab.
1 ATTN: Dr. L. C. VanAtta 1 ATTN: Mr. N. H. Enenstein 1 ATTN: Mr. John T. Milek 5 Lockheed Aircraft Corporation ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri 6 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 7 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 7 North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer ACTN: Librarian 1500 4th Street Santa Monica, California 1500 4th Street Santa Monica, Co. 1610 ATTN: Military Contrates Matthe Santa Monica, Califo		Hughes Aircraft Company	,	ATTN: Chief Engineer
1 ATTN: Mr. N. H. Enenstein 1 ATTN: Mr. John T. Milek 5 Lockheed Aircraft Corporation ATTN: Chief Engineer 2555 Hollywood Way Burbank, California 4 Republic Aviation Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri 5 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 6 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio 1 Discrict Chief California Inst. of Technology Jet Propulsion Lab.	_		2	Rand Corporation
1 ATTN: Mr. John T. Milek 5 Lockheed Aircraft Corporation ATTN: Chief Engineer 2555 Hollywood Way Burbank, California 6 McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri 6 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 7 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio 2 Raytheon Mfg. Co., ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts Waltham 54, Massachusetts Dept. Farmingdale, Long Island, New York 1 Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avene Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.				
5 Lockheed Aircraft Corporation ATTN: Chief Engineer 2555 Hollywood Way Burbank, California 3 McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri 5 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 3 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio 2 Raytheon Mfg. Co., ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts Waltham 54, Massachusetts 4 Republic Aviation Corp. ATTN: Military Contracts Dept. Farmingdale, Long Island, New York 66 Needham Street Newton Heights, Massachusetts Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avene Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.			•	
ATTN: Chief Engineer 2555 Hollywood Way Burbank, California McDonnell Aircraft Corp. ATTN: Chief Engineer F. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Dr. H. L. Thomas Waltham 54, Massachusetts Waltham 54, Massachusetts Dept. Farmingdale, Long Island, New York Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avene Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	T	Alin: Mr. John T. Milek		Santa Monica, California
2555 Hollywood Way Burbank, California McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Flant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Waltham 54, Massachusetts Republic Aviation Corp. ATTN: Military Contracts Dept. Farmingdale, Long Island, New York Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	5		2	Raytheon Mfg. Co.,
Burbank, California McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio ATTN: Mc Republic Aviation Corp. ATTN: Military Contracts Dept. Farmingdale, Long Island, New York Farmingdale, Long Island, New York ATTN: Massachusetts Farmingdale, Long Island, New York Farmingdale, Long Island, New York Attraction Corp. ATTN: Military Contracts Dept. Farmingdale, Long Island, New York 1 Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.				
McDonnell Aircraft Corp. ATTN: Chief Engineer P. 0. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland New York ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio ATTN: Military Contracts Dept. Farmingdale, Long Island, New York New York Attn: Military Contracts Dept. Farmingdale, Long Island, New York Attn: Military Contracts Dept. Farmingdale, Long Island, New York Attn: Mcliery Contracts Dept. Farmingdale, Long Island, New York 1 Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.				Waltham 54, Massachusetts
McDonnell Aircraft Corp. ATTN: Chief Engineer P. O. Box 516 Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland Now York Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: 4300 E. Fifth Avenue Columbus 16, Ohio ATTN: Military Contracts Dept. Farmingdale, Long Island, New York Farmingdale, Long Island, New York The Morkshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.		burbank, variforma	1.	Remublic Aviation Com
Lambert Municipal Airport St. Louis 3, Missouri Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland New York New 104 New 104 New 104 New 104 New York New 104 New 10	3	ATTN: Chief Engineer	4	ATTN: Military Contracts
1 Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 85 E. Joppa Road Baltimore 4, Maryland 86 Sendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 87 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 80 Section 1 THRU: Baltimore 3, Maryland 81 District Chief 10 Los Angeles Ordnance Dist. 82 North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio 8 Workshop Associates, Inc. 66 Needham Street Newton Heights, Massachusetts 8 District Avenue Boston, Massachusetts 9 THRU: 10 District Chief 10 Los Angeles Ordnance Dist. 10 Significant Solution Solu		Lambert Municipal Airport		
5 Bendix Aviation Corporation Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 3 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio 66 Needham Street Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	,	St. Louis 3, Missouri	•	
Radio Division ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland 3 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 2 North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Newton Heights, Massachusetts 1 Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: Boston, Massachusetts 1 THRU: 10 District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	5	Bendix Aviation Corporation	1	
ATTN: Mr. R. K. Thomas E. Joppa Road Baltimore 4, Maryland Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Andrew Alford Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.		Radio Division		
Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Consulting Engineers 299 Atlantic Avenue Boston, Massachusetts THRU: Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.				new oon herghos, hapsachuse ous
3 Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland 299 Atlantic Avenue Boston, Massachusetts 1 THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Airplane Plant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio 299 Atlantic Avenue Boston, Massachusetts 1 THRU: Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.			1	Andrew Alford
Glenn L. Martin Company ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Boston, Massachusetts THRU: District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.		Baltimore 4, Maryland		
ATTN: Mr. Sanford Hershfield Electronic Section Baltimore 3, Maryland North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio THRU: 1 THRU: 1 THRU: 1 Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	2	Clam 7 Mantin Commen		
Baltimore 3, Maryland District Chief Los Angeles Ordnance Dist. North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer A300 E. Fifth Avenue Columbus 16, Ohio District Chief Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.)	ATTN: Mr. Sanford Hershfield		Boston, Massachusetts
North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Los Angeles Ordnance Dist. 35 N. Raymond Avenue Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.			1	THRU:
North American Aviation, Inc. Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio 35 N. Raymond Avenue For: California Inst. of Technology Jet Propulsion Lab.		Baltimore 3, Maryland		
Airplane Plant ATTN: Chief Engineer 4300 E. Fifth Avenue Columbus 16, Ohio Pasadena 1, California FOR: California Inst. of Technology Jet Propulsion Lab.	2	North American Aviation Tra		
ATTN: Chief Engineer FOR: 4300 E. Fifth Avenue California Inst. of Technology Columbus 16, Ohio Jet Propulsion Lab.	~	Airplane Plant		
4300 E. Fifth Avenue California Inst. of Technology Columbus 16, Ohio Jet Propulsion Lab.				
Columbus 16, Ohio Jet Propulsion Lab.				
rasadem, Calliornia				Pasadena, California

DISTRIBUTION LIST Cont'd

Activities Cys

- Johns Hopkins University ATTN: Dr. Wilkes Applied Physics Lab. 8621 Georgia Avenue Silver Spring, Maryland
- 1 Massachusetts Institute of Technology ATTN: Dr. L. J. Chu Cambridge 39, Massachusetts
- 2 Polytechnic Institute of Brooklyn ATTN: Dr. A. A. Oliner 55 Johnson St., 3rd Floor Brooklyn, New York
- 2 University of Illinois ATTN: Prof. A. D. Bailey Dept. of Elec. Eng. Urbana, Illinois

University of Michigan Aeronautical Research Center Willow Run Airport Ypsilanti, Michigan

- ATTN: Dr. R. D. O'Neill ATTN: Mr. L. R. Biaselle
- 2 University of Oklahoma Research Foundation ATTN: Dr. C. L. Farrar Norman, Oklahoma

